

Fig. 1




Fig. 2




Fig. 3




Fig. 4




Fig. 5




Fig. 6




Fig. 7




Fig. 8




Fig. 9




Fig. 10




Fig. 11




Fig. 13






Fig. 12




Fig. 14




Fig. 15




Fig. 16




Fig. 17




Fig. 18




Fig. 19

160

Leica ADC HP:

Leica

Microsystems

Finish

Leica ADC HP

161

Start ADC Run

1025

Total Defects

1025

Start ADC Run

563

Defects Deleted

100.0

Defects Classified

54.0

163

164

149

147

Reduction [%]

Classifiability [%]

Report

Finish

162

165

148

31

Fig. 20




Fig. 21




Fig. 22